

**CIVIL AVIATION AUTHORITY OF THE PHILIPPINES**  
**Aircraft Accident Investigation and Inquiry Board**  
**Incident Interim Report**

**BASIC INFORMATION**

Aircraft Registration No.	:	RP-C9002
Aircraft Type/Model	:	Cessna 150M
Owner/Operator	:	Mactan Aviation
Address of Operator	:	Mactan Aviation Hangar, Gen. Aviation Area, Old Airport Road, Sasa Davao City
Date/Time of Incident	:	June 11, 2015
Type of Operation	:	Flight Training
Phase of Operation	:	Landing
Type of Occurrence	:	Nose wheel flat tire during landing
Place of Incident	:	Davao International Airport

**BRIEF DESCRIPTION OF THE EVENT:**

On or about 11 June 2015 0845H, a Cessna 150 type of aircraft with Register No. RP-C9002 owned and operated by Mactan Aviation took off from Davao International Airport for a local instructional flight. On board was a Student pilot who was released for solo flight by the flight instructor who was observing the flight from the ground. The student pilot flew the day before the incident and he had already performed four (4) “touch and go” in a row. They resumed the same activity on the following day with three touch and go before being released by the flight instructor. While on landing, the aircraft experienced a blown-up tire on its nose wheel as it touched down Runway 05, and consequently, the aircraft rolled on roughly as it was disabled and came to a stop along the active runway. The student pilot was not hurt during the incident

All the facts surrounding the event have been analyzed. The Final Report is currently being drafted and it will be published as soon as it is finalized and approved for public release.