

CIVIL AVIATION AUTHORITY OF THE PHILIPPINES
Aircraft Accident Investigation and Inquiry Board
Incident Interim Report

BASIC INFORMATION

Aircraft Registration No.	:	RP-C9914
Aircraft Type/Model	:	Airbus A321-231
Owner/Operator	:	Philippine Airlines, Inc.
Address of Operator	:	PNB Financial Center, Macapagal Avenue, CCP complex, Pasay City
Date/Time of Incident	:	January 28, 2017
Type of Operation	:	Scheduled Commercial
Phase of Operation	:	Taxi
Type of Occurrence	:	Taxiway excursion
Place of Incident	:	Kalibo International Airport

BRIEF DESCRIPTION OF THE EVENT:

On 28 January 2017, at around 1228H, Philippine Airlines Flight PR 893, an Airbus 321-231 type of aircraft with registry number RP-C9914 was involved in a taxi incident when its left hand main landing gear fell off track to the non-cemented portion of the taxiway. The flight is a scheduled passenger service from Taipei, Taiwan to Kalibo, Aklan. No injuries were reported to the Flight Crew and passengers. The aircraft landed at runway 05 of Kalibo International Airport and was instructed by the Control Tower to vacate the active runway via Taxiway Bravo for parking to Bay 3A. According to the Pilot-In-Command (PIC) who was then taxiing the aircraft, he noticed that another A321 aircraft was parked at Bay 4. As they were approaching to enter Taxiway Bravo, he opted not to follow the yellow taxiway centerline by maneuvering the aircraft further left to avoid possible collision with the parked A321 with the aircraft's wingtip. While entering the taxiway, the duty ramp marshal signaled them to stop and hold their position as the aircraft's left main landing gear fell off track to the non-cemented portion of the taxiway. The aircraft engine was shut down and the aircraft was towed towards Bay 3A. The Flight Crew and passengers sustained no injuries and disembarked normally. The aircraft was scheduled the next day for flight bound for Taipei, Taiwan after an inspection was made by the maintenance personnel and found out that the aircraft did not sustain any damage.

