

CIVIL AVIATION AUTHORITY OF THE PHILIPPINES
Aircraft Accident Investigation and Inquiry Board
S. Incident Interim Report

BASIC INFORMATION

Aircraft Registration No.	:	RP-C8613
Aircraft Type/Model	:	Airbus A320-214
Owner/Operator	:	Philippine Airlines, Inc.
Address of Operator	:	PNB FINANCIAL CENTER, Macapagal Avenue, CCP Complex, Pasay City
Date/Time of S. Incident	:	January 10, 2017
Type of Operation	:	Scheduled Commercial
Phase of Operation	:	Landing
Type of Occurrence	:	Off runway landing
Place of S. Incident	:	Kalibo International Airport, Kalibo, Aklan

BRIEF DESCRIPTION OF THE EVENT:

On 2249 (1449 UTC) 10 January 2017, an Airbus 320-214 type of aircraft with registry number RP-C8613 owned and operated by Philippine Air Lines Inc. was involved in an off runway landing at RWY 05 of Kalibo International Airport. The aircraft was cleared to land at Rwy 05 using RNAV Y approach, wind at 030 gusting 10-12 knots, and light to moderate rain shower prevailing over the station. The aircraft touchdown 485 meters away from the threshold of RWY 05 with the left landing gear at the soft grassy portion, 4.7 meters away from the side edge of the runway. It continued to make a landing roll for another 540 meters before entering the cemented portion of the runway. The Engine No. 1 air inlet cowl was damaged after colliding with the runway distance to go marker 5 and one (1) runway light was run over by the left outer main gear tire. The aircraft continued to taxi to the ramp and normal passenger deplaning was done. No injuieres were reported to the Flight Crew, Cabin Crew and passengers. The Cockpit Voice Recorder and Flight Data recorder were removed from the aircraft by the site investigator and was placed under custody of AAIB for data analysis and read out.