

CIVIL AVIATION AUTHORITY OF THE PHILIPPINES
Aircraft Accident Investigation and Inquiry Board
Accident Interim Report

BASIC INFORMATION

Aircraft Registration No.	:	RP-C1752
Aircraft Type/Model	:	Cessna 152
Owner/Operator	:	All Asia Aviation Academy
Address of Operator	:	Iba Airport, Iba, Zambales
Date/Time of Accident	:	April 1, 2016
Type of Operation	:	Flight Training
Phase of Operation	:	Landing
Type of Occurrence	:	Bounced landing that resulted to aircraft damage
Place of Accident	:	Iba Airport. Iba Zambales

BRIEF DESCRIPTION OF THE EVENT:

On April 1, 2016 at around 1100H, a Cessna 152 aircraft with registry number RP-C1752 sustained substantial damage following a bounced landing at runway 14 of Iba Airport, Iba Zambales. The student pilot lost control of the aircraft after the hard landing followed by three (3) bounces resulting to the separation of the nose gear from its attachment. The aircraft eventually went out of the runway and came to complete stop nosed over at the left side of the runway 2 meters away from the runway shoulder and around 190 meters from the initial touch down point.

The student pilot who was the sole occupant escaped unhurt. Visual meteorological condition prevailed at the time of the accident. The aircraft is being operated by All Asia Aviation Academy based in Iba, Zambales, a CAAP certified flying school to conduct flight training.

All the facts surrounding the event have been analyzed. The Final Report is currently being drafted and it will be published as soon as it is finalized and approved for public release.