

CIVIL AVIATION AUTHORITY OF THE PHILIPPINES
Aircraft Accident Investigation and Inquiry Board
Accident Interim Report

BASIC INFORMATION

Aircraft Registration No.	:	RP-C8613
Aircraft Type/Model	:	Airbus 320
Operator	:	Philippine Airlines
Address of Operator	:	Philippine Airlines, Inc. PNB Financial Center, President Diosdado P. Macapagal Avenue, CCP Complex, Pasay City
Date/Time of Accident	:	17 August 2010 / 0149UTC
Type of Operation	:	Scheduled Commercial (Passenger)
Phase of Operation	:	Landing
Type of Occurrence	:	Landed short of the runway
Place of Accident	:	Kalibo International Airport (RPVK)

BRIEF DESCRIPTION OF THE EVENT:

On August 17, 2010 at around 0149UTC, RP-C8613 an Airbus 320 type of aircraft operated by Philippine Airlines as flight PR321 sustained damage on its aft underbelly after landing short of the runway at Kalibo International Airport (RPVK). The aircraft touched down approximately 70 meters before the beginning of runway 23, and a go around was initiated. On the process, the aft under belly struck an airport perimeter fence post that resulted to 8”x 5” crack adjacent to aft cargo hold. The aircraft returned to Manila at 10,000 ft. cruising altitude due to pressurization problem. The aircraft landed safely at the Ninoy Aquino International Airport (RPLL) and no injuries were reported to 6 crew and 127 passengers.