



Republic of the Philippines  
**CIVIL AVIATION AUTHORITY OF THE PHILIPPINES**

**MEMORANDUM CIRCULAR** 011-2023

**FOR : ALL OPERATORS AND ORGANIZATIONS INVOLVED  
IN THE OPERATION AND MAINTENANCE OF TECNAM  
P2002JF AIRCRAFT**

**SUBJECT : TECNAM P2002JF 50 HOURS INSPECTIONS CHECKLIST**

**DATE : JULY 4, 2023**

An incident involving a Tecnam P2002JF type of aircraft has resulted in a Safety Recommendation where one (1) item in the 50-hour inspection specified by the aircraft manufacturer's maintenance manual was not included in an AMO's scheduled maintenance inspection checklist. The missing item was the inspection of the main landing gear attachments, bolts, and bushing for condition, especially for cracks, corrosion, looseness, and security of mounting points.

In the interest of safety and to ensure that the above has/have been complied with, all concerned operators and maintenance organizations must submit the manufacturer-specified 50-hour inspection checklist to this office or forward the same to [awd@caap.gov.ph](mailto:awd@caap.gov.ph) for evaluation.

For strict compliance.

  
**CAPTAIN MANUEL ANTONIO L. TAMAYO**  
Director General