



BID BULLETIN No. 001

PB-ILO-2025-14

June 02, 2025

Bid Bulletin No. 001, PB-ILO-2025-14 is hereby issued for the information of Prospective Bidders relative to the bidding for the project ***Repair and Maintenance of Fire Detection and Alarm System and Fire Protection System at Iloilo International Airport.***

The *Documentary Requirements* of the above-mentioned project are agreed and approved by the committee as additional Instructions to Bidders.

The Documentary Requirements will be as followed:

Project Title	Bid Opening	Scope of Work	Technical Specifications
<u>PB-ILO-2025-14</u> Repair and Maintenance of Fire Detection and Alarm System and Fire Protection System at Iloilo International Airport.	June 18, 2025, 9:00am	Please see attached	Item No. 3- Photo Electric Smoke Detector (FDK38U); approved equivalent or better

For guidance and information of all concerned.

ENGR. JOEL C. GERVERO

Chairperson

Bids and Awards Committee

Area VI

Civil Aviation Authority of the Philippines





Repair and Maintenance of Fire Detection and Alarm System

Scope of Works:

Quarterly

1. Cleaning, check-up and functional testing of the INTEGLEX Fire Alarm Control Panel including its back-up battery power supply.
2. Cleaning, check-up and functional testing of all annunciator panels.
3. Cleaning, checking and functional testing of fire alarm Manual Pull Station.
4. Cleaning, check-up and function testing of all local sounders such as Alarm Bells and Horns.
5. Checking, and function testing of all inter-phased systems (simulation/signal testing only) such as sprinkler water flow and monitor switches, pump running, pressurization, blower, smoke evacuation Fan including its status monitoring panel of dampers.

Annually

1. Cleaning, check-up and functional testing of the alarm initiating devices such as smoke/heat detectors.

Remedial Maintenance Services

1. Service calls pertaining to Equipment problems shall be available 24/7 and immediate telephone support is necessary in order to diagnose and remedy the problem with the assistance of Iloilo Airport personnel.
2. If problem unable to solve via telephone support, skilled and specialized servicemen shall be deployed immediately to site.
3. Replacement of defective devices/parts.

Note:

A service report shall be submitted after each servicing day stating the condition(s) of the different part of the system and the recommended action(s) to be done to maintain the efficiency and good running condition of equipment.

