



BID BULLETIN No. 001

PB-ILO-2025-18

June 02, 2025

Bid Bulletin No. 001, PB-ILO-2025-18 is hereby issued for the information of Prospective Bidders relative to the bidding for the project ***Repair and Maintenance of Air-Conditioning and Chiller System at Iloilo International Airport.***

The *Documentary Requirements* of the above-mentioned project are agreed and approved by the committee as additional Instructions to Bidders.

The Documentary Requirements will be as followed:

Project Title	Bid Opening	Price Schedule
<u>PB-ILO-2025-18</u> Repair and Maintenance of Air-Conditioning and Chiller System at Iloilo International Airport.	June 18, 2025, 3:30pm	Please see attached

For guidance and information of all concerned.

ENGR. JOEL C. GERVERO

Chairperson

Bids and Awards Committee

Area VI

Civil Aviation Authority of the Philippines



Name of Bidder _____ Project ID No. _____ Page ____ of ____

1	2	3	4	5	6	7	8	9
Item	Description	Country of origin	Quantity	Unit price CIF port of entry (specify port) or CIP named place (specify border point or place of destination)	Total CIF or CIP price per item (col. 4 x 5)	Unit Price Delivered Duty Unpaid (DDU)	Unit price Delivered Duty Paid (DDP)	Total Price delivered DDP (col 4 x 8)
1.0	Replacement of Defective Air Conditioning Unit at PTB CCTV Room (1unit)		1 unit					
	Floor Mounted 3TR, Inverter (1unit)							
	Labor Cost							
	Equipment Cost							
2.0	Replacement of Bearings and Pillow Block Bearing of AHU at Gangway (gate 5) and Control Tower (4units)		4 units					
	6306ZZ(japan made) (2pcs)							
	6307ZZ(japan made) (2pcs)							
	6308ZZ(japan made) (2pcs)							
	6309ZZ(japan made) (2pcs)							
	Pillow Block,P209(japan made) (4pcs)							
	Pillow Block,P211(japan made) (4pcs)							

	Labor							
3.0	General Cleaning of FCU at PTB, ADM, CTO, MNT, CPE and CPM (170units)		170 units					
	Detergent Soap 50g – 60g (220sachet)							
	Labor Cost							
	Equipment Cost							
4.0	Repainting of Corroded FCU Face Cover at ADM, MNT, CTO, CPE and CPM (55units)		55 units					
	Rust Converter (2gallon)							
	Paint, Bone Ivory(water based, quick dry enamel) (5gallon)							
	Polyester Body Filler with hardener (1gallon)							
	Steel Brush (10pcs)							
	Labor Cost							
	Equipment Cost							
5.0	Preventive Maintenance Materials (1lot)		1 lot					
	Refrigerant, R410a, 13.2 kg (2tanks)							
	Refrigerant, R32, 13.2 kg (2tanks)							
	Bearing, 6201 (Japan made) (15pcs)							
	Bearing, 6202 (Japan made) (15pcs)							
	Plastic Charol 48” x 50 yards (1roll)							
	Vblet A-47 (8pcs)							
	Vblet A-66 (3pcs)							
	Vblet B-59 (2pcs)							
	Vblet B-67 (2pcs)							
	Vblet B-94 (2pcs)							

	Eurotape 2" (9rolls)						
	WD40, 333ml (7bottles)						
	Paint latex, white (4gallons)						
	Rewinding of fan motor (2units)						
	Acoustic board, 10pcs per box (8boxes)						
	Rugs bundle, 10 pcs (8bundles)						
	10"UV-LED Water Purifier 4-stages (3sets)						
	Puller, 4" (1pc)						
	Clampmeter (1unit)						
	With true RMS AC voltage						
	Max Voltage = 600 V						
	Max Ampere = 600 A						
	Max Hertz = 500 Hz						
	PCB indoor (1set)						
	MATRIX floor mounted						
	Model No. MX-480DCI-M (Indoor)						
	TOTAL						

Name: _____

Legal Capacity: _____

Signature: _____

Duly authorized to sign the Bid for and behalf of: _____

Date:_____

[shall be submitted with the Bid if bidder is offering goods from within the Philippines]

[shall be submitted with the Bid if bidder is offering goods from within the Philippines]

For Goods Offered from Within the Philippines

Name of Bidder _____ Project ID No. _____ Page ____ of ____

1	2	3	4	5	6	7	8	9	10
Item	Description	Country of origin	Quantity	Unit price EXW per item	Transportation and all other costs incidental to delivery, per item	Sales and other taxes payable if Contract is awarded, per item	Cost of Incidental Services, if applicable, per item	Total Price, per unit (col 5+6+7+8)	Total Price delivered Final Destination (col 9) x (col 4)
1.0	Replacement of Defective Air Conditioning Unit at PTB CCTV Room (1unit)		1 unit						
	Floor Mounted 3TR, Inverter (1unit)								
	Labor Cost								
	Equipment Cost								
2.0	Replacement of Bearings and Pillow Block Bearing of AHU at Gangway (gate 5) and Control Tower (4units)		4 units						
	6306ZZ(japan made) (2pcs)								
	6307ZZ(japan made) (2pcs)								

	6308ZZ(japan made) (2pcs)								
	6309ZZ(japan made) (2pcs)								
	Pillow Block,P209(japan made) (4pcs)								
	Pillow Block,P211(japan made) (4pcs)								
	Labor								
3.0	General Cleaning of FCU at PTB, ADM, CTO, MNT, CPE and CPM (170units)		170 units						
	Detergent Soap 50g – 60g (220sachet)								
	Labor Cost								
	Equipment Cost								
4.0	Repainting of Corroded FCU Face Cover at ADM, MNT, CTO, CPE and CPM (55units)		55 units						
	Rust Converter (2gallon)								
	Paint, Bone Ivory(water based, quick dry enamel) (5gallon)								
	Polyester Body Filler with hardener (1gallon)								
	Steel Brush (10pcs)								
	Labor Cost								
	Equipment Cost								
5.0	Preventive Maintenance Materials (1lot)		1 lot						
	Refrigerant, R410a, 13.2 kg (2tanks)								
	Refrigerant, R32, 13.2 kg								

	(2tanks)		
	Bearing, 6201 (Japan made) (15pcs)		
	Bearing, 6202 (Japan made) (15pcs)		
	Plastic Charol 48" x 50 yards (1roll)		
	Vblet A-47 (8pcs)		
	Vblet A-66 (3pcs)		
	Vblet B-59 (2pcs)		
	Vblet B-67 (2pcs)		
	Vblet B-94 (2pcs)		
	Eurotape 2" (9rolls)		
	WD40, 333ml (7bottles)		
	Paint latex, white (4gallons)		
	Rewinding of fan motor (2units)		
	Acoustic board, 10pcs per box (8boxes)		
	Rugs bundle, 10 pcs (8bundles)		
	10"UV-LED Water Purifier 4- stages (3sets)		
	Puller, 4" (1pc)		
	Clampmeter (1unit)		
	With true RMS AC voltage		
	Max Voltage = 600 V		
	Max Ampere = 600 A		
	Max Hertz = 500 Hz		
	PCB indoor (1set)		
	MATRIX floor mounted		
	Model No. MX-480DCI-M		

	(Indoor)								
	TOTAL								

Name: _____

Legal Capacity: _____

Signature: _____

Duly authorized to sign the Bid for and behalf of: _____

Date:_____