



Republic of the Philippines  
**CIVIL AVIATION AUTHORITY OF THE PHILIPPINES**

22 November 2022

Date

**REQUEST FOR QUOTATION**

---



---



---

Sir/Madam:

Please quote your lowest net prices, taxes, including Government discount terms, and period of delivery of the following items listed hereunder for the account of the official use of the Civil Aviation Authority of the Philippines (CAAP), Area Center V, Bicol International Airport in connection with the implementation of the **Repair Of Various Service Vehicles At Bicol International Airport** project. It is requested that price quotations be submitted in an envelope, duly sealed, to be opened by our Bids and Awards Committee on **29 November 2022 at 2:00 pm** at the BAC Office, Ground Floor, Admin Bldg, Bicol International Airport (BIA), Daraga, Albay.

ITEM NO.	UNIT	QTY.	DESCRIPTION (Location : BIA, Daraga, Albay	UNIT PRICE	TOTAL
<b>I. ISUZU DMAX: SAA-8372</b>					
<b>A. Materials</b>					
1	Unit	1	Auxiliary Fan		
2	Unit	1	Evaporator		
3	Unit	1	Expansion Valve		
4	Unit	1	Fan Motor Blower		
5	Unit	1	Condenser		
6	Unit	1	Receiver Drier		

ITEM NO.	UNIT	QTY.	DESCRIPTION (Location : BIA, Daraga, Albay)	UNIT PRICE	TOTAL
<b>I. ISUZU DMAX: SAA-8372 (Continuation)</b>					
<b>B. Scope of work</b>					
1	Lot	1	Fabrication, alignment and painting of rear bumper		
2	Lot	1	Change of tint from light color to dark color 2 sides (left & right)		
3	Lot	1	Check, replace worn out parts of air conditioning system to serviceable		
4	Lot	1	Repair, replace bulb of strobe light and wiring		
<b>Sub-Total</b>					
<b>II. MITSUBISHI STRADA: SHY - 990 (Pick-Up)</b>					
<b>A. Materials</b>					
1	Unit	1	Expansion Valve		
2	Unit	1	Drier		
3	Unit	1	Evaporator		
4	Pc	1	Fan Belt		
<b>B. Scope Of Work</b>					
1	Lot	1	Replacement of Aircon Compressor		
2	Lot	1	Replace door handle (Driver's Side)		
3	Lot	1	Replace Engine Timing Belt		
4	Lot	1	Repair and retouch painting of rear bumper		
<b>Sub-Total</b>					

ITEM NO.	UNIT	QTY.	DESCRIPTION (Location : BIA, Daraga, Albay)	UNIT PRICE	TOTAL
<b>III. TOYOTA HI-ACE: A9F-653</b>					
<b>A. Scope Of Work</b>					
1	Lot	1	Repair, alignment & retouch painting of right side railing		
2	Lot	1	Repair, alignment & retouch of left side fender		
3	Lot	1	Replace tint from light color to dark color of left, right, and rear portion		
4	Lot	1	Replace side mirror (Driver's Side)		
5	Lot	1	Convert, replace power window to manual (Left and Right)		
<b>Sub-Total</b>					
<b>IV. TOYOTA HI-ACE: A8-P811</b>					
<b>A. Scope Of Work</b>					
1	Lot	1	Replace tint color from light color to dark color of left, right, and rear portion		
2	Lot	1	Convert unserviceable power window, replace to manual handle (Left & Right Door)		
<b>Sub-Total</b>					
<b>V. TOYOTA REVO: SFG-674</b>					
<b>A. Materials</b>					
1	Unit	1	2SM Battery (Replacement)		
<b>Sub-Total</b>					
<b>GRAND TOTAL</b>					
<i>x-x-x-x- Nothing Follows-x-x-x-x-x</i>					



The following should be submitted together with the quotation:

1. Current Mayor's/Business Permit;
2. Phil-GEPS Registration Number;
3. Name/credentials of proposed Auto Mechanic;
4. Brochures/pictures of materials/spare parts to be used indicating brand names and specifications; and
5. Omnibus Sworn Statement (*see attached format, maybe submitted together with the quotation or before issuance of Notice of Award.*)


**Quotations not accompanied by current Mayor's/Business Permit; name/credentials of proposed Auto Mechanic; Phil-GEPS Registration Number; and brochures with brand names and specifications of materials/spare parts shall be automatically disqualified.**

Prices must be quoted in Philippine Peso and must include the unit price and total price, inclusive of all taxes to be paid and other incidental cost to the delivery sites if the contract is awarded. Quotations must be delivered to the Civil Aviation Authority of the Philippines, Area Center V **not later than 2:00 p.m. on 29 November 2022** at its physical address at the BAC Office, Ground Floor Admin Bldg., Bicol International Airport, Daraga, Albay. **Online submission is not allowed and late submission shall not be accepted.**

All quotations together with the required documents should be placed in a **sealed envelope** marked **Repair Of Service Vehicles At Bicol International Airport.**

The Approved Budget for the Contract (ABC) is **One Hundred Ninety Eight Thousand Fifty Pesos (Php 198,050.00)**. No. of Days to Complete: **Twenty (20) calendar days.**

Very truly yours,

  
**EPIFANIO O. PRINIA, JR.**  
Chairperson, Bids and Awards Committee

**MR. EPIFANIO O. PRINIA, JR.**  
Chairperson, Bids and Awards Committee  
Civil Aviation Authority of the Philippines  
Bicol International Airport, Daraga, Albay

Sir:

In connection with the above Request for Quotation, I/We propose to furnish deliver in conformity with specification of the articles in which I/We quoted, and insofar as controlled items are concerned, the price quotation I/We have made in accordance with those approved by the Price Control Council.

\_\_\_\_\_  
Signature Over Printed Name of Dealer/Supplier

-----  
**TO WHOM IT MAY CONCERN:**

This is to certify that I have personally served this Request for Quotation for **Repair Of Various Service Vehicles At Bicol International Airport** to the above-named dealer/supplier in accordance with the existing regulations.

\_\_\_\_\_  
Canvasser