



SUMMARY OF AERODROME DATA

| Airport | Category | Critical Aircraft | ICAO Code | Designation | Nearest Equivalent or Higher Category Airport | Runway | | | | Taxiway | | | | Apron | | | PTB | | | Tower | |
|---|--------------|--------------------|-----------|--------------------------|---|------------------|-----------|--|---|--|----------|-------------------------------|-------------|---------------------------|-----------|-----------------------------|-------------------|------------------------------|---------------|-------|----------------|
| | | | | | | Dimension | Surface | Obstacles along approach/ departure surface published on AIP | Remarks | Dimension (Length x Width) | Surface | No. Of Taxiway/s | Description | Dimension (Width x Depth) | Surface | No. Of Parking Bay (Stands) | Dimension (sq.m.) | Airconditioning Unit | Toilet Status | | |
| AREA CENTER X | | | | | | | | | | | | | | | | | | | | | |
| With Commercial Flight Operation | | | | | | | | | | | | | | | | | | | | | |
| 69 | Laguindingan | Principal Class I | A320 | RPMY | 09/27 | Butuan | 2100 x 45 | Concrete | No obstacles on both approach surface (09/27) | 521.621 | 203 x 23 | Concrete | 2 | Stubs | 355 x 130 | Concrete | 6 | 7,184 | with ACU | OK | Tower 8-storey |
| 70 | Ozamis | Principal Class I | A320 | RPMO | 03/21 | Dipolog/Pagadian | 1893 x 45 | Concrete with Asphalt Overlay | No obstacles on both approach surface (03/21) | Extended NOTAM; Exercise caution during landing/take-off due to WIP. | 65 x 18 | Concrete with Asphalt Overlay | 2 | 45 degrees | 194 x 80 | Concrete | 4 | 972 | with ACU | OK | FSS 2-storey |
| 71 | Camiguin | Principal Class II | Q400 | RPMH | 07/25 | Laguindingan | 1367 x 30 | Concrete with Asphalt Overlay | No obstacles on both approach surface (07/25) | | 42 x 20 | Concrete | 1 | 45 degrees | 96 x 54 | Concrete | 2 | 639 Departure 750 Arrival | with ACU | Ok | None |
| No Commercial Flight Operation | | | | | | | | | | | | | | | | | | | | | |
| 72 | Iligan | Community | GenAv | RPMI | 02/20 | Laguindingan | 1400 x 18 | Concrete | No published obstacle in AIP | | 40 x 18 | Concrete | 2 | stubs | 100 x 40 | Concrete | 2 | 320 | without ACU | Ok | None |
| 73 | Wao | Community | GenAv | Not yet published in AIP | 18/36 | | 1000 x 30 | Macadam | No published obstacle in AIP | Not Yet Operational | None | None | None | None | None | None | None | None | None | None | None |
| 74 | Malabang | Community | GenAv | RPMM | 06/24 | Cotabato | 1300 x 36 | Concrete | No published obstacle in AIP | | None | None | None | None | 100 x 150 | Concrete | 2 | None | None | None | None |

Note : Extension of NOTAM issued for **OZAMIS AIRPORT** Exercise caution during landing/take-off due to Work In Progress (WIP) - Runway Strip Grade Correction until April 11, 2022.