

Republic of the Philippines CIVIL AVIATION AUTHORITY OF THE PHILIPPINES

SUMMARY OF AERODROME DATA

							Runway				Taxiway				Apron			PTB			
	Airport	Category	Critical Aircraft	ICAO Code	Designation	Nearest Equivalent or Higher Category Airport	Dimension	Surface	Obstacles along approach/ departure surface published on	Remarks	Dimension (Length x Width)	Surface	No. Of Taxiway/s	Description	Dimension (Width x Depth)	Surface	No. Of Parking Bay (Stands)	Dimension (sq.m.)	Airconditionin g Unit	Toilet Status	Tower
Α	REA CENTER XII	-				•	•			•			•			•	<u>-</u>				-
W	ith Commercial Flig	ht Operati	ion																		
8	1 Butuan	Principal Class I	A320	RPME	12/30	Laguindinga n	2096 x 45	Concrete with Asphalt Overlay	No obstacle on both approach surface (09/27)		72 x 18	Concrete	2	45Deg	250 x 100	Concrete	4	1,734	with ACU	ОК	Tower 4- storey
8	2 Si argao	Principal Class II	Q400	RPNS	01/19	Surigao	1347 x 30	Concrete	Presence of House, cluster of trees on both approach 01/19		2 - 55 x 18 1 - 40 x 18	Concrete	3	2 - 45 degrees 1 - Stub	180 x 50	Concrete	4	648	with ACU	Ok	FSS 4- Storey
8	3 S urigao	Principal Class II	Q400	RPMS	18/36	Butuan	1705 x 30	Concrete with Asphalt Overlay	No obstacles on both approach surface (18/36)	Airport Operation Hours is back to 8:00AM - 4:00PM ; Effective Immediately	65 x 18	Concrete	3	45 degrees	230 x 60	Concrete	3	960	with ACU	Ok	FSS 2 Storey
N	o Commercial Flight	Operation	n																		
8	4 Tandag	Principal Class II	Q400	RPMW	03/21	Butuan	1360 x 30	I I	Presence of hill on approach 03, Power line on approach 21	Runway 03/21 work in Progress (Runway Extension including Provision of Stopway and Runway Strip Grade Correction)	72 x 18	Concrete	1	stubs	90 x 55	Concrete	1	350	with ACU	Ok	FSS 2 Storey
8	5 Bislig	Community	GenAv/ Cessna Caravan or equivalent	RPMF	05/23	Tandag	1200 x 30	Concrete	Presence of Trees on approach 05		66 x 18	Concrete	1	stub	80 x 75	Concrete	2	350	None	Ok	None

* NOTAM C1351/21 issued for Surigao Airport stating Airport Temporary Hours of Operations CANCEL effective immediately.

^{*}Extended NOTAM C1074/21 issued for Surigao Airport stating until September 24, 2021 until March 21, 2022. Parking Bay 3 and Taxiway Charlie is closed due to Work in Progress (Reblocking of Apron - Phase 1).

^{*} Extended NOTAM C1041/21 issued for Siargao Airport until March 09, 2022.

^{*} Siargao Airport - Airport Temporary Hours of Operations is from 6:00AM to 6:00PM.

^{*}Extended NOTAM C1141/21 issued for TANDAG Airport until March 27, 2022. Runway 03/21 Work in Progress (Runway Extension including Provision of Stopway and Runway Strip Grade Correction).