



SUMMARY OF AERODROME DATA

Airport	Category	Critical Aircraft	ICAO Code	Designation	Nearest Equivalent or Higher Category Airport	Runway				Taxiway				Apron			PTB			Tower	
						Dimension	Surface	Obstacles along approach/ departure surface published on AIP	Remarks	Dimension (Length x Width)	Surface	No. Of Taxiway/s	Description	Dimension (Width x Depth)	Surface	No. Of Parking Bay (Stands)	Dimension (sq.m.)	Airconditioning Unit	Toilet Status		
<b>AREA CENTER VII</b>																					
<b>With Commercial Flight Operation</b>																					
45	<b>Bohol - Panglao</b>	Principal Class I	A321	RPSP	03/21	Mactan - Cebu	2500 x 45	Asphalt	Cluster of coconut Trees on both approach surface (03/21)		290 x 23	Concrete with Asphalt Overlay	2	stubs	330 x 150	Concrete	7	13,884	with ACU	OK	Tower 9-storey
46	<b>Dumaguete</b>	Principal Class I	A320	RPVD	09/27	Mactan - Cebu	1845 x 45	Concrete with Asphalt Overlay	Cluster of Trees at approach surface 09	408m Displacement at RWY 09 due to obstruction	A - 68 x 20 B - 70 x 20	Concrete	2	45Deg	270 x 100	Concrete	4	1,216	with ACU	OK	FSS 4-storey
<b>No Commercial Flight Operation</b>																					
47	<b>Siquijor</b>	Community	GenAv/ Cessna Caravan or equivalent	RPVZ	04/22	Dumaguete	1040 x 30	Concrete	Presence of Trees and Electrical post on both approach (04/22)	160m displacement at RWY 04 due to runway extension; Ongoing DPWH 400m runway Extension	47 x 18	Concrete	1	stubs	65 x 40	Concrete	1	640	None	Ok	None
48	<b>Ubay</b>	Community	GenAv	RPSN	05/23	Panglao	1100 x 18	Concrete	No published obstacle in AIP, however there's a presence of high tension electric post at approach 05	Closed	None	None	None	None	None	None	None	None	None	None	None
49	<b>Bantayan (Operated by MCIAA)</b>	Community	GenAv/ Cessna Caravan or equivalent	RPSB	16/34	MCIA	1200 x 18	Concrete	No published obstacle in AIP	MCIAA Operated Airport	None	None	None	None	60 x 80	Macadam	1	80 (Terminal Shed)	without ACU	No Data Available	None

\* Extended NOTAM C0990/21 issued for **SIQUIJOR AIRPORT** until February 28, 2022. Temporary Declared Distance is 1,040m x 30m. Displaced by 160m at RWY 04 due to runway extension.

\* Extended NOTAM C0991/21 issued for **DUMAGUETE AIRPORT** until February 28, 2022. Temporary Declared Distance is 1,845m x 30m. Displaced by 408m at RWY 09 due to obstruction.