



SUMMARY OF AERODROME DATA

Airport	Category	Critical Aircraft	ICAO Code	Designation	Nearest Equivalent or Higher Category Airport	Runway				Taxiway				Apron			PTB			Tower	
						Dimension	Surface	Obstacles along approach/ departure surface published on AIP	Remarks	Dimension (Length x Width)	Surface	No. Of Taxiway/s	Description	Dimension (Width x Depth)	Surface	No. Of Parking Bay (Stands)	Dimension (sq.m.)	Airconditioning Unit	Toilet Status		
<b>AREA CENTER IX</b>																					
<b>With Commercial Flight Operation</b>																					
60	Pagadian	Principal Class I	A320	RPMP	02/20	Zamboanga	2000 x 45	Concrete	No obstacles on both approach surface (02/20)		118 x 16	Concrete	2	45 degrees	150 x 75	Concrete	2	857	with ACU	OK	FSS 2-storey
61	Zamboanga	Principal Class I	A320	RPMZ	09/27	Davao/Gensan	2609 x 45	Concrete with Asphalt Overlay	No published obstacle in AIP	800m Displacement at RWY 09 due to ongoing upgrading of runway	A - 68 x 18 B - 103 x 24	Concrete	2	1 - Stubs 1 - Rapid	350 x 150	Concrete	4	3,628.80	with ACU	OK	Tower 5-storey
62	Dipolog	Principal Class I	A320	RPMG	02/20	Laguindingan	1913 x 45	Concrete with Asphalt Overlay	Presence of communications tower, antennae, houses and trees on both approaches		A - 70 x 23 B - 65 x 23	Concrete	2	45Deg	198 x 105	Concrete	3	1,776	with ACU	OK	FSS 3-storey
63	Sanga-sanga	Principal Class I	320	RPMN	02/20	Zamboanga	1860 x 45	Concrete with Asphalt Overlay	Cluster of coconut Trees and Electric post at approach 20	Extension and Expansion of Runway up to 1,860m by USAID - CY 2009	None	None	None	None	70 x 50	Concrete	1	130	with ACU	OK	FSS 2-storey
<b>No Commercial Flight Operation</b>																					
64	Jolo	Principal Class II	Q400	RPMJ	09/27	Zamboanga	1800 x 30	Concrete	Oneway approach, Mountain at approach 27	Usable Runway length 1,200m; 600m temporary displacement due to WIP at RWY 09;	50 x 24 49 x 24	Concrete	2	45 degrees	150 x 60	Concrete	2	240	with ACU	OK	None
65	Siocon	Community	GenAv/ Cessna Caravan or equivalent	RPNO	09/27	Zamboanga	600 x 18	Concrete/Macadam	No published obstacle in AIP	60m - Concrete; Rest - Macadam	None	None	None	None	80 x 60	Macadam	1	120 (Terminal Shed)	None	Ok	None
66	Ipil	Community	GenAv/ Cessna Caravan or equivalent	RPMV	18/36	Zamboanga	975 x 30	Concrete	No published obstacle in AIP; However presence of structures on approach of rwy 16		None	None	None	None	60 x 120	Concrete	1	677 (Newly Constructed)	None	Ok	None
67	Liloy	Community	GenAv	RPMX	05/23	Dipolog	574 x 30	Macadam	No published obstacle in AIP		None	None	None	None	None	None	None	None	None	None	None
68	Cagayan de Sulu (Mapun)	Community	GenAv	RPMU	13/31	Puerto Princesa	1300 x 30	Macadam	No published obstacle in AIP		None	None	None	None	60 x 50	Macadam	1	None	None	None	None

\*Note: Extended NOTAM C1142/21 issued for **JOLO AIRPORT** until March 27, 2022. Available Runway length is 1,200 meters. Runway 09 Threshold is displaced by 600 meters due Work in Progress (Widening and Grading of Runway).

\*Note: Extended NOTAM C0792/21 issued for **ZAMBOANGA AIRPORT** until January 21, 2022. Available Runway Length is 1,800m x 45m. Due WIP (Reblocking of Runway, Repair of Potholes, Asphalt Overlay).