



INVITATION FOR PRICE QUOTATION

Date: 12 October 2022

For The

**Repair & Maintenance Of Windcone Stand
Including Concrete Base Slab At Virac Airport-2nd SVP**

The Civil Aviation Authority of the Philippines (CAAP), Area Center V, Bicol International Airport intends to apply the estimated amount of **Two Hundred Ninety Nine Thousand Nine Hundred Forty Nine Pesos & 51/100 (Php 299,949.51)** for the **Repair & Maintenance Of Windcone Stand Including Concrete Base Slab At Virac Airport -2nd SVP** project.

The CAAP now requests you to submit price quotation on the item listed below, subject to the Specification and Terms and Conditions provided hereunder.

1. All entries must be printed.
2. Number of days to complete: Forty One (41) calendar days.
3. Bid must be complete and award will be made on a lump sum basis.
4. Price validity shall be for a period of One Hundred Twenty (120) calendar days.
5. The following should be submitted together with the quotation:
 - 5.1 Valid PCAB License Small A;
 - 5.2 Current Mayor's/Business Permit;
 - 5.3 Phil-GEPS Registration Number; and
 - 5.4 Name/credentials of proposed Construction Foreman, and Safety Officer.
 - 5.5 List of Contractor's Equipment (One Bagger Cement Mixer, Bar Cutter, Oxy-acetylene Cutting Torch and Portable Welding Machine)
(The contractor's major equipment units, which are owned, leased, and/or under purchase agreements must be supported by proof of ownership, certification of availability of equipment from the equipment lessor/vendor for the duration of the project, as the case may be, which must meet the minimum requirements
6. Other documentary requirements:
 - 6.1 Omnibus Sworn Statement *(see attached format, maybe submitted together with the quotation or before issuance of Notice of Award.)*
 - 6.2 Additional Requirements to be submitted *before issuance of Notice To Proceed:*
 - 6.2.1 Work Schedule;
 - 6.2.2 PERT/CPM;
 - 6.2.3 S-Curve;
 - 6.2.4 Manpower Schedule;
 - 6.2.5 Work Method;
 - 6.2.6 Construction Safety & Health Programs Approved by the DOLE* ; and
 - 6.2.7 Performance Security.


Quotations not accompanied by valid PCAB License; current Mayor's/Business Permit; Phil-GEPS Registration Number; name/credentials of proposed Construction Foreman, and Safety Officer; and list of contractor's equipment together with supporting documents shall be automatically disqualified.

Your prices must be quoted in Philippine Peso and must include the unit price and total price, inclusive of all taxes to be paid and other incidental cost to the delivery sites if the contract is awarded. Quotations must be delivered to the Civil Aviation Authority of the Philippines, Area Center V not later than **2:00 p.m. on 21 October 2022** at its physical address at the BAC Office, Ground Floor Admin Bldg., Bicol International Airport, Daraga, Albay. **Online submission is not allowed and late submission shall not be accepted.**

All quotations together with the required documents should be placed in a sealed envelope marked **Repair & Maintenance Of Windcone Stand Including Concrete Base Slab At Virac Airport-2nd SVP.**

For further inquiries you may call:

THE BAC SECRETARIAT
BAC Office, G/F Admin Building
Civil Aviation Authority of the Philippines
Area Center V, Bicol International Airport
Daraga, Albay
Telephone Nos. 0906-410-2901
Email Ad.: legazpiairport.bac@gmail.com


EPIFANIO O. PRINIA, JR.
Chairperson
Bids & Awards Committee
BAC Office
Ground Floor, Admin Bldg.
Bicol International Airport
Daraga, Albay

Admin Bldg, Bicol International Airport, Daraga, Albay, Philippines, 4501
BAC Office Tel Nos.: 0906-410-2901
Tel. Hotline Nos.: 0915-197-0819 / 0928-958-4841; area_center5@caap.gov.ph; www.caap.gov.ph