

# Republic of the Philippines CIVIL AVIATION AUTHORITY OF THE PHILIPPINES

12 July 2022 Date

# REQUEST FOR QUOTATION

Sir/Madam:

Please quote your lowest net prices, taxes, including Government discount terms, and period of delivery of the following items listed hereunder for the account of the official use of the Civil Aviation Authority of the Philippines (CAAP), Area Center V, Bicol International Airport in connection with the implementation of the **Repair Of Terminal Building At Bacon Airport** project. It is requested that price quotations be submitted in an envelope, duly sealed, to be opened by our Bids and Awards Committee on 20 July 2022 at 2:00 pm at the BAC Office, Ground Floor, Admin Bldg, Bicol International Airport (BIA), Daraga, Albay.

The following should be submitted together with the quotation:

- Valid PCAB License Small A;
- 2. Current Mayor's/Business Permit;
- 3. Phil-GEPS Registration Number; and
- 4. Name/credentials of proposed Construction Foreman, and Safety Officer.
- 5. Other documentary requirements:
- 5.1 Omnibus Sworn Statement (see attached format, maybe submitted together with the quotation or before issuance of Notice of Award.)
- 5.2 Additional Requirements to be submitted before issuance of Notice To Proceed:
  - 7.2.1 Work Schedule;
  - 7.2.2 PERT/CPM:
  - 7.2.3 S-Curve;
  - 7.2.4 Manpower Schedule;
  - 7.2.5 Work Method:
  - 7.2.6 Construction Safety & Health Programs Approved by the DOLE\*; and
  - 72.7 Performance Security.

<sup>\*</sup>Copy of the CSHP received by the DOLE may be initially submitted together with the NOA, however, the DOLE approved CSHP must be immediately submitted upon approval.

Quotations not accompanied by valid PCAB License; current Mayor's/Business Permit; Phil-GEPS Registration Number; and name/credentials of proposed Construction Foreman, and Safety Officer shall be automatically disqualified.

## SCOPE OF WORK:

1.) Site preparation including provision of 3'x2' project billboard.

2.) Site Works:

Removal of the old glass & cleaning the area.

3.) Civil Works:

Concreting of sidewalk (see plans for details).

4.) Repainting Works:

1-coat Primer and 2-coats Top Coat for interior & exterior wall including sanding (Flat Latex & Top

Coat).

2-coats Top Coat for roofing (Roof Guard).

Application of Rust Remover for Steel Windows.

2-coats Primer & 2-coats Top Coat for steel windows (Red Oxide & QDE).

5.) Steel Windows:

Installation of the new glass including sealant application. (see plans for details).

- 6.) Provision of minor tools and equipments necessary for the execution of work.
- 7.) Incidentals shall be charged on the OCM provided/incorporated in this Program of Works.
- 8.) Turn-over of waste materials to Airport authority.

# PLEASE ACCOMPLISH THE FOLLOWING ATTACHED FORMS:

- Bid Proposal (Annex "A")
- 2. Bill Of Quantities (Annex "B")
- 3. Detailed Estimate Form (Annex "C")

### NOTE:

All pages of the Annexes must be duly signed by the bidder or his authorized representative. Bids/quotations not addressing or providing all of the required items where applicable shall be considered non-responsive and thus, automatically disqualified. In this regard, where a required item is provided, but no price is indicated, the same shall be considered non-responsive, but specifying a zero (0) or a dash (-) for the said item would mean that it is being offered for free.

(Contractor's Logo On Main Page)

# BID PROPOSAL

# Repair Of Terminal Building At Bacon Airport

ITEM	DESCRIPTION OF WORK	QUANTIT	N F	QUANTIT UNI ESTIMATED	MARK-UPS IN PERCENT	ARK-UPS IN PERCENT	TOTAL	TOTAL MARK-UP	VAT	TOTAL	TOTAL TOTAL COST UNIT COST	UNIT COST
NO.		ĭ	-	DIRECT COST	OCM Profit	Profit	%	VALUE		COST		
(1)	(2)	(3)	(4)	(5)	(9)	(7)	(8)	(9) (5) x (8)	(9) (10) (5) x (8) 5% X ((5) + (9)]	(11)	(12)	(13)
1.00	1.00 CIVIL WORKS	1.00	lot									
2.00	ARCHITECTURAL WORKS											
2.01	2.01 PAINTING WORKS	1.00	lot									
2.02	2.02 STEEL WINDOW	1.00	lot						3			
				n-	- nothing follows -	lows -						
	TOTAL AMOUNT											

Submitted by:	Printed Name:	osition	lame Company:	20

Annex "B"

(Contractor's Logo On Main Page)

# BILL OF QUANTITIES

Project: Repair Of Terminal Building At Bacon Airport

Location: Bacon, Sorsogon City

Item No	Description	Qty	Unit	Unit Price	Amount
1.00	Civil Works				5,,500,000,000
2.00	Architectural Works				
2.01	Painting Works				
	Pesos Amount in Words	1.00	lot		
	and centavos				
2.02	Steel Window				
	Pesos Amount in Words	1.00	lot		
	and centavos				

Total Bid Amount (Php):			
Total Bid Amount in Words:			
	Submitted by:		
	Printed Name:		
	Position:		
	Name Company:		
	Date:		

Annex "C"

(Contractor's Logo On Main Page)

NAME OF PROJECT

Repair Of Terminal Building At Bacon Airport

LOCATION

: Bacon, Sorsogon City

SUBJECT

: Bill of Quantities

ITEM	DESCRIPTION	ON	QUANTITY	UNIT	UNIT PRICE	AMOUNT
1.00	CIVIL WORKS					71,110 0711
1.01	CONCRETE WORKS					
A	MATERIAL COST					
	Sidewalk					
	Cement		40.00	bag		
	Sand		3.00	m³		
	Gravel		6.00	m³		
	RSB 10mmØ		44.00	pc		
	Tie Wire		2.00	kg		
	Forms & Scaffoldings:					
	Ordinary Plywood 1/4" Thk.		2.00	pc		
	Coco Lumber 2"x2"		14.00	bdft		
	Common Nails Assorted		1,00	kg		
				Material Cost		
В	LABOR COST		QTY	DUR. (DAYS)	RATE/DAY	
	Skilled Labor		1	9		
	Common Labor		2	9		
				Labor Cost		
A	TOTAL MATERIAL COST					
В	TOTAL LABOR COST					
C	TOTAL EQUIPMENT COST					
D	TOTAL DIRECT COST					
		INDIR	ECT COSTS			
I. OCN	THE RESIDENCE OF STREET, TO SECOND STREET, STR	15.0%	of Estimated I	Direct Cost		
	TRACTOR'S PROFIT	10.0%	of Estimated I	Direct Cost		
-	AL OCM & PROFIT	25.0%	of D			
	UE ADDED TAX, (VAT)	5.0%	of(D+E)			
	AL ESTIMATED INDIRECT COS					
	AL ESTIMATED UNIT INDIRECT	COST (G/Qua	intity), P/Unit			
OTAL	ESTIMATED COST (D+G), P					

Submitted by:	
Printed Name:	
Position:	
Name Company:	
Date:	

(Contractor's Logo On Main Page)

NAME OF PROJECT

: Repair Of Terminal Building At Bacon Airport

LOCATION

: Bacon, Sorsogon City

SUBJECT

: Bill of Quantities

TEM	The second secon	ON	QUANTITY	UNIT	UNIT PRICE	AMOUNT
2.00	ARCHITECTURAL WORKS				O. T. T. T. T. C. E.	AMOUNT
2.01	PAINTING WORKS					
A	MATERIAL COST					
	Interior & Exterior Wall					
	Flat Latex Paint		18	gal		
	Latex Paint (Semi-Gloss)		36	gal		
	Sand Paper, #100		3	m		
	Lacquer Thinner		1	gal		
	Roller Brush, 7"		2	ре		
	Paint Brush, 4"		2	pc		
	Ceiling			•		
	QDE Paint (Semi-Gloss)		2	gal		
	Roller Brush, 7"		1	pc		
	Paint Brush, 4"		1	pc		
	Roofing			8.0		
	Roofguard		10	gal		
	Paint Brush, 4"		2	рс		
	Steel Window			***		
	QDE Paint (Semi-Gloss)		2	gal		
	Rust Remover		3	gal		
	Paint Brush, 4"		2	рс		
	Steel Brush		2	рс		
			Material Cost		3	
В	LABOR COST		QTY	DUR (DAYS)	RATE/DAY	
	Skilled Labor		2	9	KAIEDAI	
	Common Labor		4	9		
				3 1		
4 .	TOTAL MATERIAL COOP		Labor Cost			
	TOTAL MATERIAL COST TOTAL LABOR COST					
- 1	FOTAL PURECT COST					-
D '	TOTAL DIRECT COST	INDID	POT COSTS			
OC	M	15.0%	ECT COSTS	1		
	NTRACTOR'S PROFIT	10.0%	of Estimated D			
_	TAL OCM & PROFIT	25.0%	of Estimated D	rect Cost		
	LUE ADDED TAX, (VAT)	5.0%	of D			
	TAL ESTIMATED INDIRECT CO		of (D + E)			
	TAL ESTIMATED INDIRECT CO		postitu) Dati t			
	L ESTIMATED COST (D+G), P		iunaty), P/Unit			
	L ESTIMATED UNIT COST (Total					

Submitted by:	
Printed Name:	
Position:	
Name Company:	
Date:	

Annex "C"

(Contractor's Logo On Main Page)

NAME OF PROJECT

: Repair Of Terminal Building At Bacon Airport

LOCATION

: Bacon, Sorsogon City

SUBJECT

: Bill of Quantities

ITEM	DEDCRIT II	ON	QUANTITY	UNIT	UNIT PRICE	AMOUNT
2.00	ARCHITECTURAL WORKS				- THICE	AMOUNT
	Site Works:					
	Steel Window 30pcs ±0.40m	$X \pm 0.55m$ panels				
	4pcs ±0.40m	$X \pm 0.40m$ panels)				
	Removal of the old glass & clea	ning the area	1.00	lot		
				Labor Cost		
2.02	STEEL WINDOW					
A	MATERIAL COST					
	Steel Window					
	5mm thk Tempered Glass Pane					
	$30 pcs \pm 0.40$	m X ±0.55m panels	7.70	$m^2$		
		X ±0.40m panels)				
	Glass Sealant, 300ml		16.00	tube		
	Glass Sealant Gun		2.00	рс		
	Lunen coor		N	Interial Cost		
В	LABOR COST		QTY	DUR. (DAYS)	RATE/DAY	
	Skilled Labor		2	8		
	Common Labor		2	8		
				Labor Cost		
	TOTAL MATERIAL COST					
	TOTAL LABOR COST					
	TOTAL EQUIPMENT COST					
D .	TOTAL DIRECT COST					
		INDIREC	CT COSTS			
. OCN		15.0%	of Estimated D	irect Cost		
	NTRACTOR's PROFIT	10.0%	of Estimated D	irect Cost		
10.10	AL OCM & PROFIT	25.0%	of D			
_	UE ADDED TAX, (VAT)	5.0%	of $(D + E)$			
	AL ESTIMATED INDIRECT COS	The state of the s				
	AL ESTIMATED UNIT INDIREC	T COST (G/Quantit	y), P/Unit			
	ESTIMATED COST (D+G), P					
OTAL	ESTIMATED UNIT COST (Total	Estimated Cost / Qua	ntity), P/Unit			

Submitted by:	
Printed Name:	
Position:	
Name Company:	
Date:	

Your prices must be quoted in Philippine Peso and must include the unit price and total price, inclusive of all taxes to be paid and other incidental cost to the delivery sites if the contract is awarded. Quotations must be delivered to the Civil Aviation Authority of the Philippines, Area Center V not later than 2:00 p.m. on 20 July 2022 at its physical address at the BAC Office, Ground Floor Admin Bldg., Bicol International Airport, Daraga, Albay. Online submission is not allowed and late submission shall not be accepted.

All quotations together with the required documents should be placed in a sealed envelope marked Repair of Terminal Building At Bacon Airport.

The Approved Budget for the Contract (ABC) is Two Hundred Forty Nine Thousand Nine Hundred Forty One Pesos & 19/100 (Php 249,941.19). No. of Days to Complete: Thirty (30) calendar days.

Very truly yours,

EPIFANIO O. PRINIA, JR.

Chairperson, Bids and Awards Committee

## MR. EPIFANIO O. PRINIA, JR.

Chairperson, Bids and Awards Committee Civil Aviation Authority of the Philippines Bicol International Airport, Daraga, Albay

Sir:

In connection with the above Request for Quotation, I/We propose to furnish deliver in conformity with specification of the articles in which I/We quoted, and insofar as controlled items are concerned, the price quotation I/We have made in accordance with those approved by the Price Control Council.

Signature Over Printed Name of Dealer/Supplier

## TO WHOM IT MAY CONCERN:

This is to certify that I have personally served this Request for Quotation for Repair of Terminal Building At Bacon Airport to the above-named dealer/supplier in accordance with the existing regulations.

Canvasser