



Republic of the Philippines

## CIVIL AVIATION AUTHORITY OF THE PHILIPPINES

DATE: September 24, 2024

### REQUEST FOR QUOTATION

The **CIVIL AVIATION AUTHORITY OF THE PHILIPPINES-AREA X**, through its Canvass and Contract Committee (CCC), now invites interested contractors/ suppliers to submit their Price Quotations for the Project **REPAIR/MAINTENANCE OF SIDES VMA 105 FIRETRUCK AND HINO FIRETRUCK AT CAMIGUIN AIRPORT**, with their quantities, and for their respective use and end user:

Quantity/ Unit	Items	Purpose	Office/ Unit/ Airport User	Approved Budget of Contract
1 Unit 1 Pc 2 L 2 L 7 Yard 3 m 5 m 3 L 2 Set 3 Pail  1 Assy 1 Pail 1 Set 1 Set  1 Set 1 Set 4 Tube 3 Pc 10	Brake Valve Drain Plug with Washer Fiberglass Resin Hardener Gasa Matting Sanding Block No. 80 Sand Paper No. 80 Solvent Cleaner Mixing Cups and Sticks Gold Ultra Engine Oil SAE 15W-40 with Filter Kit Toyota Fuel Pump Assembly Coolant Piston Ring Over Size 0.25 Connecting Ro Bearing (Standard) Main Bearing Standard Overhauling Gasket Silicon Gasket Gasket Silac Engine Oil SAE 15W-40 with filter	For repair/main tenance VMO Firetruck and Hino Firetruck	Camiguin Airport	PhP <b>94,794.00</b>

**Deadline of Submission:** September 30, 2024 at 10:00 A.M

Bidding will be conducted through open competitive bidding procedures using a non-discretionary "pass/fail" criterion as specified in the Implementing Rules and Regulations (IRR) of Republic Act (RA) 9184, otherwise known as the "Government Procurement Reform Act".

Further, the prospective suppliers should possess the following:



Republic of the Philippines

## CIVIL AVIATION AUTHORITY OF THE PHILIPPINES

1. Should have the legal capacity to enter into business or to perfect contracts (with updated Business Permit from DTI and recent Tax Certification from BIR as per Section 8.5 of Section 8.0 of Rule III and as per sub-paragraph a.ii of Section 24.1 of Section 24 of Rule VIII of the Revised IRR of RA 9184 and GPPB Resolution No. 11-2013 dated April 26, 2013);
2. Notarized Omnibus Sworn Statement
3. PhilGeps Registration Certificate (At least Red Membership)
4. Should not be among those blacklisted suppliers. (as per sub- sub-paragraph a.iv (1) of Section 25.2 of Section 25 of Rule VIII of the Revised IRR of RA 9184 and Section 2 of GPPB's UNIFORM GUIDELINES FOR BLACKLISTING OF MANUFACTURERS, SUPPLIERS, DISTRIBUTORS, CONTRACTORS AND CONSULTANTS)

The **CIVIL AVIATION AUTHORITY OF THE PHILIPPINES (CAAP)- AREA X** reserves the right to accept or reject any bid, to annul the bidding process, and to reject all bids at any time prior to contract award, without thereby incurring any liability to the affected bidder or bidders.

For further information, please refer to:

**CAROLINA C. ADANZA**

CCC-Secretary

Ground Floor, Admin Building

Laguindingan Misamis Oriental Airport


Laguindingan, Misamis Oriental

CAAP Area X

Telephone: (088)-555-1881 to 84 (Local 1210)

0915-56-89246

*Signed:*

  
**JOHN ROYELL Z. SIJO**  
MHCU Chief Supervisor  
CCC Chairperson