

22 November, 2024 Date

REQUEST FOR QUOTATION

Sir/Madam:
Please quote your lowest net prices, taxes, including Government discount terms, and

Please quote your lowest net prices, taxes, including Government discount terms, and period of delivery of the following items listed hereunder for the account of the official use of the Civil Aviation Authority of the Philippines (CAAP), Area Center V, in connection with the implementation of the Repair And Maintenance Of Existing Restroom At Bicol International Airport - 3rd SVP project. It is requested that price quotations be submitted in an envelope, duly sealed, to be opened by our Canvass and Contract Committee (CCC) not later than 2:00 p.m. on 28 November, 2024 at the CAAP's physical address at the BAC/CCC Office, Ground Floor, Admin Bldg., Bicol International Airport (BIA), Daraga, Albay.

The following should be submitted together with the quotation:

- Current Mayor's/Business Permit;
- 2. Phil-GEPS Registration Number;
- 3. Valid PCAB License Small B Category C & D;
- 4. Name/credentials of proposed One (1) Construction Foreman, and One (1) Master Electrician;
- 5. Other documentary requirements:
 - 5.1 Omnibus Sworn Statement

(see attached format, maybe submitted together with the quotation or before issuance of Notice of Award.)

Quotations not accompanied by current Mayor's/Business Permit, Phil-GEPS Registration Number; Valid PCAB license; and Name/credentials of proposed Construction Foreman and Master Electrician shall be automatically disqualified.







SCOPE OF WORK

1. Site Works

- a. Provision of safety barricade during construction.
- b. Removal and relocation/reinstallation of affected fixtures for the installation of drop ceiling.

2. Architectural Works

- a. Installation and painting of drop ceiling above countertops (verify to plans for detail and location).
- b. Installation of wall cladding (verify to plans for location).
- c. Repainting of ceiling on toilets.

3. Electrical Works

- a. Supply and installation of additional lighting fixtures above countertop (tap to nearest power supply).
- 4. Provision of minor tools, materials and equipments not included on itemized breakdown to be charge to OCM.

PLEASE ACCOMPLISH THE FOLLOWING ATTACHED FORMS:

- 1. Bid Proposal (Annex "A")
- 2. Bill Of Quantities (Annex "B")
- 3. Detailed Estimate Form (Annex "C")

NOTE:

All pages of the Annexes must be duly signed by the bidder or his authorized representative. Bids/quotations not addressing or providing all of the required items where applicable shall be considered non-responsive and thus, automatically disqualified. In this regard, where a required item is provided, but no price is indicated, the same shall be considered non-responsive, but specifying a zero (0) or a dash (-) for the said item would mean that it is being offered for free.





Republic of the Philippines

CIVIL AVIATION AUTHORITY OF THE PHILIPPINES

Bid Proposal (Annex "A")

(Contractor's Logo On Main Page)

BID PROPOSAL

Repair and Maintenance of Existing Restroom at BIA - 3rd SVP

Bicol International Airport, Daraga, Albay

ITEM		VEIENALIO	FINI	ESTIMATED MARK-UPS IN TOTAL MARK-UP	MARK	UPS IN	TOTAL	L MARK-UP	T4//	TOTAL	TOTAL	TOOTHINI
9	DESCRIPTION OF WORK	COAN III ONI	200	DIRECT COST OCM Profit	OCM	Profit	%	VALUE	۸۸	INDIRECT COST	IOTAL COST	OINII COSI
(1)	167	Ĉ	8	(5)	9	6	(8)	(6)	(10)	(11)	(12)	(13)
Ξ	(7)	(c)	f)	6	<u>6</u>	(3)	6	$(2) \times (8)$	2% X [(5) + (9)]	(9) + (10)	(5) + (11)	(12)/(3)
1.00	1.00 SITE WORKS	1.00	lot									
2.00	2.00 ARCHITECTURAL WORKS	1.00	ot									
2.10	2.10 Carpentry Works	1.00 lot	lot									
2.20	2.20 Painting Works	1.00 lot	lot									
3.00	3.00 ELECTRICAL WORKS	1.00 lot	lot									
	TOTAL AMOUNT											

Signature:

		any:	
Printed Name:	Position:	Name of Company:	Date:

Bicol International Airport, Alobo, Daraga Albay, Philippines, 4501









Bill Of Quantities (Annex "B")

(Contractor's Logo On Main Page)

BILL OF QUANTITIES

Project: Repair And Maintenance Of Existing Restroom At Bicol International Airport - 3rd

Location · Ricol International Airport, Aloho, Daraga, Albay

Item No	Description	Qty	Unit	Unit Price	Amount
1.00	SITE WORKS				
	Pesos Amount in Words	1.00	lot		
	and centavos				
2.00	ARCHITECTURAL WORKS				
	Pesos Amount in Words	1.00	lot		
	and centavos	-			
2.10	Carpentry Works				
	Pesos Amount in Words	1.00	lot		
	and centavos				
2.20	Painting Works				
	Pesos Amount in Words	1.00	lot		
	and centavos				
3.00	ELECTRICAL WORKS	-			
	Pesos Amount in Words	1.00	lot		
	and centavos	-			

Total Bid Amount (Php) :		
Total Bid Amount in Words:		
	Signature:	
	Printed Name:	
	Position:	
	Name of Company:	
	Date:	











Detailed Estimate Form (Annex "C")

(Contractor's Logo On Main Page)

NAME OF PROJECT

Repair and Maintenance of Existing Restroom at BIA - 3rd SVP

LOCATION

Bicol International Airport, Daraga, Albay

SUBJECT

Bill of Quantities

ITEM	DESCRIPTION	QUANTITY	UNIT	UNIT PRICE	AMOUN1
1.00	SITE WORKS				
	Site Enclosure/Barricade				
Α	Materials				
	Sacoline with framing	15.00	sq.m		
			Material Cos	t	
	Removal and relocation of affected fixtures on ceiling				
В	Labor Cost	QTY	DUR. (DAYS)	RATE/DAY	
	Skilled Laborer	1.00	3.00		
	Common Laborer	1.00	3.00		
	Consider A till collaboration of model to be sub-dep		Labor Cost		
C	Equipment Cost				
	Scaffolding Set/ Ladder	1.00	3.00		
			Equipment C	ost	
Α	TOTAL MATERIAL COST			*	
В	TOTAL LABOR COST				

- C TOTAL EQUIPMENT RENTAL COST
- D **TOTAL DIRECT COST**

	INDIR	ECT COSTS	
1. OCM	15.0%	of Estimated Direct Cost	
2. CONTRACTOR'S PROFIT	10.0%	of Estimated Direct Cost	
E. TOTAL OCM & PROFIT	25.0%	of D	
F. VALUE ADDED TAX, (VAT)	5.0%	of (D + E)	
G. SUB-TOTAL ESTIMATED INDIRE	CT COST (F+E),	P	
H. SUB-TOTAL ESTIMATED UNIT I	NDIRECT COST (G	/ Quantity), P/Unit	
SUB-TOTAL ESTIMATED COST (D	+ G), P		
SUB-TOTAL ESTIMATED UNIT COS	ST (Total Estimate	ed Cost / Quantity), P/Unit	





2.00	ARCHITECTURAL WORKS				
2.10	Carpentry Works				
Α	Materials				
	Drop Ceiling				
	4mm thk x 4' x 8' Fiber Cement Board	8.00	pcs.		
	12mm thk x 4' x 8' MR Gypsum Board	2.00	pcs.		
	Wall Angle, 25mmx25mmx3.0mx0.50mm thk	36.00	pcs.		
	Metal Furring, 50mm x 19mm x 0.6mm x 5m	12.00	pcs.		
	Blind Rivet	205.00	pcs.		
	Black Screw	103.00	pcs.		
	PVC Wall Cladding				
	WPC Indoor Flutted Panel, 202mmx30mmx2.85m	24.00	pcs	*	
	Metal Clip for Flutted Panel	48.00	pcs		
	No More Nail	2.00	tube		
	Screw	96.00	pcs		
			Material Cos	t	
В	Labor Cost	QTY	DUR. (DAYS)	RATE/DAY	
	Foreman	1.00	7.00		
	Skilled Laborer	1.00	7.00		
	Common Laborer	1.00	7.00		
			Labor Cost		
С	Equipment Cost				
	Scaffolding Set/ Ladder	1.00	6.00		
			Equipment C	ost	

- Α **TOTAL MATERIAL COST**
- В **TOTAL LABOR COST**
- C TOTAL EQUIPMENT RENTAL COST
- D **TOTAL DIRECT COST**

INDIRECT COSTS					
1. OCM	15.0%	of Estimated Direct Cost			
2. CONTRACTOR'S PROFIT	10.0%	of Estimated Direct Cost			
E. TOTAL OCM & PROFIT	25.0%	of D			
F. VALUE ADDED TAX, (VAT)	5.0%	of (D + E)			
G. SUB-TOTAL ESTIMATED INDIRE	CT COST (F+E),	P			
H. SUB-TOTAL ESTIMATED UNIT I	NDIRECT COST (G	i / Quantity), P/Unit			
SUB-TOTAL ESTIMATED COST (D	+ G), P				
SUB-TOTAL ESTIMATED UNIT COS	T (Total Estimate	ed Cost / Quantity), P/Unit			







2.00	ARCHITECTURAL WORKS				
2.20	Painting Works				
Α	Materials				
	Drop Ceiling				
	Flat Latex Paint	8.00	gals		
	Elastomeric Paint	3.00	gals		
	Gypsum Putty	3.00	gals		
	Paper Joint Tape for Drywall, 2"x250ft	1.00	pcs		
	Baby Roller with pan	8.00	pcs		
	Paint Brush 2"	10.00	pcs		
	Rugs	2.00	kgs		
	Ceiling Repainting				
	Flat Latex Paint	6.00	gals		
			Material Cos	t	
В	Labor Cost	QTY	DUR. (DAYS)	RATE/DAY	
	Foreman	1.00	4.00		
	Skilled Laborer	1.00	4.00		
	Common Laborer	1.00	4.00		
			Labor Cost		

- **TOTAL MATERIAL COST**
- В **TOTAL LABOR COST**
- C **TOTAL EQUIPMENT RENTAL COST**
- D **TOTAL DIRECT COST**

	INDIR	ECT COSTS	
1. OCM	15.0%	of Estimated Direct Cost	
2. CONTRACTOR'S PROFIT	10.0%	of Estimated Direct Cost	
E. TOTAL OCM & PROFIT	25.0%	of D	
F. VALUE ADDED TAX, (VAT)	5.0%	of (D + E)	
G. SUB-TOTAL ESTIMATED INDIRE	CT COST (F+E),	P	
H. SUB-TOTAL ESTIMATED UNIT I	NDIRECT COST (i / Quantity), P/Unit	
SUB-TOTAL ESTIMATED COST (D	+ G), P		
SUB-TOTAL ESTIMATED UNIT CO	T (Total Estimate	ed Cost / Quantity), P/Unit	





3.00	ELECTRICAL WORKS				
3.10	Electrical Supply and Fixtures				
Α	Materials				
	120mm dia. Surface Mounted Downlight Frosted	32.00	pcs		
	Type Black Casing with 3W Bulb (warm white)	32.00	P		
	3.5 mm ² THHN/THWN-2 600V 90°C Copper Wire,	128.00	m		
	Lead Free Type, (UL) Listed				
	PVC Juntion Box, 4"x4"	32.00	pcs		
	PVC Flexible Hose 1/2"	30.00	lm		
			Material Cos	t	
В	Labor Cost	QTY	DUR. (DAYS)	RATE/DAY	
	Master Electrician	1.00	7.00		
	Common Laborer	1.00	7.00		
			Labor Cost		

- TOTAL MATERIAL COST
- В **TOTAL LABOR COST**
- C **TOTAL EQUIPMENT RENTAL COST**
- **TOTAL DIRECT COST** D

INDIRECT COSTS			
1. OCM	15.0%	of Estimated Direct Cost	
2. CONTRACTOR'S PROFIT	10.0%	of Estimated Direct Cost	
E. TOTAL OCM & PROFIT	25.0%	of D	
F. VALUE ADDED TAX, (VAT)	5.0%	of (D + E)	
G. SUB-TOTAL ESTIMATED INDIRI	CT COST (F+E),	P	
H. SUB-TOTAL ESTIMATED UNIT INDIRECT COST (G / Quantity), P/Unit			
SUB-TOTAL ESTIMATED COST (D + G), P			
SUB-TOTAL ESTIMATED UNIT COST (Total Estimated Cost / Quantity), P/Unit			

Signature :	
Printed Name:	
Position:	
Name of Company:	
Date:	







Your prices must be quoted in Philippine Peso and must include the unit price and total price, inclusive of all taxes to be paid and other incidental cost to the delivery site if the contract is awarded. Quotations will be opened in the presence of the Bidders' representatives who choose to attend at the address provided. Quotations must be delivered to the Civil Aviation Authority of the Philippines, Area Center V at its physical address at the BAC/CCC Office, Ground Floor Admin Bldg., Bicol International Airport, Daraga, Albay not later than 2:00 p.m. on 28 November 2024. Online submission is not allowed and late quotations shall not be accepted. All quotations together with the required documents should be placed in a sealed envelope marked Repair And Maintenance Of Existing Restroom At Bicol International Airport - 3rd SVP.

TERMS OF REFERENCE

Name of Project	Repair And Maintenance Of Existing Restroom At Bicol International Airport - 3rd SVP.
Approved Budget	One Hundred Ninety-Nine Thousand Nine Hundred Eight Pesos and 19/100 (PHP 199,908.19)
Number of Days to Complete	Forty One (41) Calendar Days
Location/s	Bicol International Airport, Alobo, Daraga, Albay





Contractor's Obligation	The Contractor shall carry out the works properly and in accordance with the Contract. The Contractor shall provide all supervision, labor, materials, plant and equipment required for the project.
	2. The Contractor shall commence execution of the works immediately upon the receipt of Notice to Proceed and shall carry out the works in accordance with the Contract Agreement. The Contractor shall complete the project per approved Contract time of Forty One (41) Calendar Days.
	3. The Contractor shall be responsible for the safety of all activities on the Site.
	4. The Contractor shall carry out all instructions of the Procuring Entity's Representative that comply with the applicable laws where the Site is located.
Liquidated Damages	The Contractor shall pay liquidated damages to the Procuring Entity at the rate per day of delay. The applicable liquidated damages is at least one tenth (1/10) of one percent of the cost of the unperformed portion for every day of delay.

Very truly yours,



Canvass and Contract Committee







EPIFANIO O. PRINIA, JR.

Chairperson, Canvass and Contract Committee Civil Aviation Authority of the Philippines Bicol International Airport Daraga, Albay

Sir:

In connection with the above Request for Quotation, I/We propose to furnish deliver in conformity with specification of the articles in which I/We quoted, and insofar as controlled items are concerned, the price quotation I/We have made in accordance with those approved by the Price Control Council.

Signature Over Printed Name of Dealer/Supplier

TO WHOM IT MAY CONCERN:

This is to certify that I have personally served this Request for Quotation for the project **Repair** And Maintenance Of Existing Restroom At Bicol International Airport - 3rd SVP to the abovenamed dealer/supplier in accordance with the existing regulations.

LINDA MARIE D. OGENA

Canvasser

