



05 May, 2025 Date

REQUEST FOR QUOTATION

Sir/Madam:

Please quote your lowest net prices, taxes, including Government discount terms, and period of delivery of the following items listed hereunder for the account of the official use of the Civil Aviation Authority of the Philippines (CAAP), Area Center V, in connection with the implementation of the Repair And Maintenance Of BIA Air-Handling System At Bicol International Airport - 2nd SVP project. It is requested that price quotations be submitted in an envelope, duly sealed, to be opened by our Canvass and Contract Committee (CCC) not later than 2:00 p.m. on 09 May 2025 at the CAAP's physical address at the BAC/CCC Office, Ground Floor, Admin Bldg., Bicol International Airport (BIA), Daraga, Albay.

The following should be submitted together with the quotation:

- 1. Current Mayor's/Business Permit;
- Phil-GEPS Registration Number;
- List of completed similar contracts within the last three (3) years which must be related to preventive or corrective maintenance of air-handling units with attached supporting documents;
- 4. List of Contractor's Equipment, including proof of ownership or certification of availability of Minor Tools & Equipment, Special Tools and Ladder & Scaffolding, from the lessor/vendor for the duration of the project, as the case may be; and
- 5. Name/credentials of proposed one (1) Electrical/Mechanical Engineer and Two (2) Service Technician;
- 6. Other documentary requirements:
 - 6.1. Omnibus Sworn Statement

(see attached format, maybe submitted together with the quotation or before issuance of Notice of Award.)





Republic of the Philippines

CIVIL AVIATION AUTHORITY OF THE PHILIPPINES

Quotations not accompanied by current Mayor's/Business Permit; Phil-GEPS Registration Number; List of completed similar contracts within the last three (3) years which must be related to preventive or corrective maintenance of air-handling units with attached supporting documents; List of Contractor's Equipment, including proof of ownership or certification of availability from the lessor/vendor for the duration of the project, as the case may be (Minor Tools & Equipment, Special Tools and Ladder & Scaffolding); and Name/credentials of proposed personnel - one (1) Electrical/Mechanical Engineer and Two (2) Service Technician, shall be automatically disqualified.

SCOPE OF WORK

REPAIR AND MAINTENANCE OF AIR-HANDLING UNITS (AHU NO. 5 AND AHU NO. 7)

- 1. Supply, delivery and installation of AHU Midea Cabinet control display. Including restoration, reprogramming of PLC as needed and testing and commisioning of AHU No. 7 functions.
- 2. Supply, delivery and installation of Fan Belt for AHU No. 5. Including rectification of unusual sound and vibrations.

INSTALLATION OF EXHAUST DUCTING FOR ROOFTOP PACKAGE UNIT (RTU)

- 1. Mobilization and pre-fabrication/installation Inspection.
- 2. Fabrication of ductings and supports.
- 3. Onsite assembly and installation of ducting, hangers and supports.
- 4. Installation of insulation.
- 5. Testing and commissioning.

Note: Inclusive of one (1) year warranty for parts/components and workmanship.

PLEASE ACCOMPLISH THE FOLLOWING ATTACHED FORMS:

- 1. Bid Proposal (Annex "A")
- 2. Bill Of Quantities (Annex "B")
- 3. Detailed Estimate Form (Annex "C")

NOTE:

All pages of the Annexes must be duly signed by the bidder or his authorized representative. Bids/quotations not addressing or providing all of the required items where applicable shall be considered non-responsive and thus, automatically disqualified. In this regard, where a required item is provided, but no price is indicated, the same shall be considered non-responsive, but specifying a zero (0) or a dash (-) for the said item would mean that it is being offered for free.



00





Republic of the Philippines CIVIL AVIATION AUTHORITY OF THE PHILIPPINES

Bid Proposal (Annex "A")

(Contractor's Logo On Main Page)

Repair and Maintenance of BIA Air-Handling System - 2nd SVP

Bicol International Airport, Daraga, Albay

ITEM	ITEM DESCRIPTION OF WORK NO.		UNIT	ESTIMATED	MARK-	UPS IN	TOTA	L MARK-UP	VAT	TOTAL	TOTAL COST	UNIT COST
NO.				DIRECT COST	OCM	Profit	%	VALUE		INDIRECT COST		
(1)	(1) (2)		(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
(3)								(5) x (8)	5% X [(5) + (9)]	(9) + (10)	(5) + (11)	(12)/(3)
1.00	1.00 REPAIR AND MAINTENANCE OF AHU		lot									
	TOTAL AMOUNT											-

Signature:	
Printed Name:	
Position:	
Name of Company:	
Date:	





Unit

Bill Of Quantities (Annex "B")

Amount

Unit Price

(Contractor's Logo On Main Page)

BILL OF QUANTITIES

Qty

Project:

Item No

Repair And Maintenance Of BIA Air-Handling System At Bicol International

Airport - 2nd SVP

Location: Bicol International Airport

Description

1	Repair And Maintenance of Al-	IU			
	Pesos Amount in Words	1.00	lot		
	and centavos				
Total Bi	d Amount (Php) :				
Total Bi	d Amount in Words:				
		Signature:			
		Printed Name:			
		Position:			
	Name of Company:				
		Date:			





Republic of the Philippines

CIVIL AVIATION AUTHORITY OF THE PHILIPPINES

Detailed Estimate Form (Annex "C")

(Contractor's Logo On Main Page)

Repair and Maintenance of BIA Air-Handling System - 2nd SVP Bicol International Airport, Daraga, Albay NAME OF PROJECT

LOCATION

EM	DESCRIPTION	QUANTITY	UNIT	UNIT PRICE	AMOUN
	REPAIR AND MAINTENANCE AHU				
A	Materials Supply and delivery				
	Supply and delivery				
	Air-Handling Unit Cabinet Display	1.00	Unit		
	MIDEA, Model: TPC7032KT				
	Fan Belt	2.00	Unit		
	SPA 1357LW	0.070.8 (0.00)			
	Mitsuboshi Anti-static Oil & Heat Resistant				
			Material Cos	t	
.00	INSTALLATION OF EXHAUST DUCT FOR RTU				-
A	Materials				
	GI Sheet #22	22.00	Pc		
	Polyolefin 15mm x 1.2m x 15m	2.00	Roll		
	TDC Angle Corner	90.00	Pc		
	Nuts and Washers 3/8	65.00	Pc		
	Duct Clip (1")	90.00	Pc		
	Duct Gasket Tape (1")	10.00	Roll		
	Vulcaseal	2.00	Gal		
	Angle Bar (1 1/2" x 1 1/2" x 3/16")	10.00	Pc		
	Threaded Bar (3/8)	10.00	Pc		
	Welding rod	2.00	Kg		
	Anchorbolt (3/8)	20.00	Pc		
	Duct Tape	10.00	Roll		
	Epoxy Primer	1.00	Gal		
	Paint Thinner	0.50	Gal		
	Paint Brush 2"	4.00	Pc		
	Drill Bits 3/8"	2.00	Pc		
	Cutting Disc 14"	3.00	box		
	Angle Grinder Disc 4"	50.00	Pc		
	Air Grille (800mm x 500mm)	1.00	Pc		
			Material Cos	t	
		QTY	UNIT	RATE	AMOUNT
В	Labor Cost	4		12.11	
	Installation of Air-Handling Unit Cabinet Display and Fan belt	1.00	Lot		
	Note: Dismontling of defective components also included.				
	Fabrication, assembly and installation of 800mm x	1.00			
	500mm x 21m Rectangular Ducting and insulation.	1.00	Lot		
	Installation of support brackets and hangers	1.00	Lot		
	Chipping/sleeving works, Ceiling removal and restoration	1.00	Lot		
	Note: Includes mobilization & demobilization, technical supervision, labor works, equipment & scaffold rentals, minor consummables, provision of				
	special tools and equipment, testing and commissioning.				
	Please see scope of work.				
	riedde dee deupe of work.			Ti.	











- A TOTAL MATERIAL COST
- B TOTAL LABOR COST
- C TOTAL EQUIPMENT RENTAL COST
- D TOTAL DIRECT COST

	INDIRECT	COSTS			
1. OCM	8.0%	of Estimated Direct Cost			
2. CONTRACTOR'S PROFIT	5.0%	of Estimated Direct Cost			
E. TOTAL OCM & PROFIT	13.0%	of D			
F. VALUE ADDED TAX, (VAT)	5.0%	of (D + E)			
G. SUB-TOTAL ESTIMATED INDIREC	T COST (F + E), P				
H. SUB-TOTAL ESTIMATED UNIT INI	DIRECT COST (G / Quantit	y), P/Unit			
SUB-TOTAL ESTIMATED COST (D +	G), P				
SUB-TOTAL ESTIMATED UNIT COST (Total Estimated Cost / Quantity), P/Unit					

Signature:	
Printed Name:	
Position:	
Name of Company:	
Date:	

Your prices must be quoted in Philippine Peso and must include the unit price and total price, inclusive of all taxes to be paid and other incidental cost to the delivery site if the contract is awarded. Quotations will be opened in the presence of the Bidders' representatives who choose to attend at the address provided. Quotations must be delivered to the Civil Aviation Authority of the Philippines, Area Center V at its physical address at the BAC/CCC Office, Ground Floor Admin Bldg., Bicol International Airport, Daraga, Albay not later than 2:00 p.m. on 09 May 2025. Online submission is not allowed and late quotations shall not be accepted. All quotations together with the required documents should be placed in a sealed envelope marked Repair And Maintenance Of BIA Air-Handling System At Bicol International Airport - 2nd SVP.








Republic of the Philippines

CIVIL AVIATION AUTHORITY OF THE PHILIPPINES

TERMS OF REFERENCE

Name of Project	Repair And Maintenance Of BIA Air-Handling System At Bicol International Airport - 2nd SVP				
Approved Budget	Four Hundred Twenty-Eight Thousand Two Hundred Eighty- One Pesos and 53/100 (Php. 428,281.53)				
Number of Days to Complete	Seventy-Five (75) Calendar Days				
Location/s	Bicol International Airport				
Contractor's Obligation	1. The Contractor shall carry out the works properly and in accordance with the Contract. The Contractor shall provide all supervision, labor, materials, plant and equipment required for the project.				
	2. The Contractor shall commence execution of the works immediately upon the receipt of Notice to Proceed and shall carry out the works in accordance with the Contract Agreement. The Contractor shall complete the project per approved Contract time of Seventy-Five (75) Calendar Days.				
	The Contractor shall be responsible for the safety of all activities on the Site.				
	4. The Contractor shall carry out all instructions of the Procuring Entity's Representative that comply with the applicable laws where the Site is located.				
Liquidated Damages	The Contractor shall pay liquidated damages to the Procuring Entity at the rate per day of delay. The applicable liquidated damages is at least one tenth (1/10) of one percent of the cost of the unperformed portion for every day of delay.				

Very truly yours,



Charperson, Canvass and Contract Committee











EPIFANIO O. PRINIA, JR.

Chairperson, Canvass and Contract Committee Civil Aviation Authority of the Philippines **Bicol International Airport** Daraga, Albay

Sir:

In connection with the above Request for Quotation, I/We propose to furnish deliver in conformity with specification of the articles in which I/We quoted, and insofar as controlled items are concerned, the price quotation I/We have made in accordance with those approved by the Price Control Council.

Signature Over Printed Name of Dealer/Supplier

TO WHOM IT MAY CONCERN:

This is to certify that I have personally served this Request for Quotation for the project Repair And Maintenance Of BIA Air-Handling System At Bicol International Airport - 2nd SVP to the above-named dealer/supplier in accordance with the existing regulations.



